MEASUREMENT BOOK

BR 1556306117

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of Work: Improvements to roads and drains at Navy Layout in Bagalakunte in W.No 14 T. Dasarahalli Sub-div						
	JOB code No 014-17-000033 Estcost Rs 20.00 Lakhs				Pcode No P-3158		
	Work order No BBMP/EE/DD/WO/124/2017-18 dt 21.6.17						
	Agency: Technical Manager (W) M.R.I.D.L						
	Measurements Recorded on						
	(1) Earth work Excavation by manual means in ordinary soil in volving an average horizontal throw upto 2mt & av lift 1.50 mt						

M. A. R. 57 (Rule 116)
Measurement Book

No. B 180037

al No. .....
e of work ..... From ..... To .....
e of Contractor of nature of Agency.....
of commencement of work.....

Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
excavated surface levelled and sides neatly dressed the disposed earth to be levelled neatly after breaking of clods complete as per Sp. with all lead & lifts including conveying the Excavated earth silt debris & OAD earth to lead of 0 to 9KM distance by using private vehicle this includes cost & loading and unloading charges etc complete as per Sp.						
Qty vide I.N.O (1) pre-measurements recorded vide p.No 180094 & this MB				504.90 cft	170.92 cft	86297 = 51

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	including reflectorising glass beads at 250 grams per Sqmt area thickness of 2.5 m.m is Exclusive of Surface applied glass beads as per IRC : 35 the finished surface to be level uniform and free from streaks & holes complete as per Spn						
	Qty vide I.NO (9) Pre-measurements recorded in P.NO 180098 of this MB					22.95 M2	
						at Rs 542.77/-	12455=41
	Add G/. K.R.I.D.L Charges						183094=
							16478=
						Total	199573=9

183094=00
16478=00
199572=00

This grading Checked & Found Correct

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರರು
ಟಿ.ಡಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

M. A. R. 57 (Rule 116)
Measurement Book

No. B 180042

No. .....

of work ..... From ..... To .....

of Contractor of nature of Agency.....

of commencement of work.....

Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
1) certified that the work done Satisfactorily						
2) certified that the debris removed from the work spot						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರರು
ಟಿ.ಡಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

MEASUREMENT BOOK

M. A. R. 57 (Rule
Measurement Bo

No. B 180043

No. .....

e of work ..... From ..... To .....

e of Contractor of nature of Agency.....

of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

Navy Layout

93.3 mts
Road No 3

Road No 2
90.0 mts

Road No 4
60.0 mts

Road 1
156.00 mts

Index
Asphalting to Roads

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ.ಬಾ.ಕರಡಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
		BR 155/30/6/17			0.315		

Audited and admitted for Rs. 199720-00
Passed by Cheque for Rs. 183103-00

by adjust... Rs. 16627-00

Accounts Superintendent
B.S.M.P. Dasarahalli Division

Exe. Engineer